



PIC16F87/88

PIC16F87/88 Rev. B1 Silicon/Data Sheet Errata

The PIC16F87/88 Rev. B1 parts you have received conform functionally to the Device Data Sheet (DS30487B), except for the anomalies described below.

All of the issues listed here will be addressed in future revisions of the PIC16F87/88 silicon.

The following silicon errata apply only to PIC16F87/88 devices with these Device/Revision IDs:

Part Number	Device ID	Revision ID
PIC18F87	00 0111 001	00101
PIC16F88	00 0111 011	00101

1. Module: Internal RC Oscillator

A high Sleep current will exist when the following condition is met and procedures are followed:

CONDITION: FOSC<2:0> (Configuration Word Register 1) bits are configured for any oscillator selection other than the internal RC oscillator.

PROCEDURE:

1. Clock switch occurs anywhere in the application code where the internal RC oscillator is selected via the SCS bits ('10').
2. Sleep mode is entered while the SCS bits are configured for the internal RC oscillator ('10').

Work around

Before Sleep mode is entered, configure or clear the SCS bits ('00') to switch back to the primary clock source that is defined by FOSC<2:0> (Configuration Word Register 1).

PIC16F87/88

2. Module: Internal RC Oscillator IOFS bit

The device data sheet states when an INTOSC frequency is selected (125, 250, 500 kHz, 1, 2, 4, 8 MHz), the frequency will be stable when the IOFS bit becomes set (IOFS = 1) at 4 ms. The following applies for applications relying on time dependent code.

Under the following conditions, any of the INTOSC frequencies may not be stable when IOFS becomes set (IOFS = 1). Devices may vary from one to the next and may take as long as 60 ms to become stable.

1. Wake from Sleep, internal RC oscillator is selected via the SCS bits or Configuration Word 1 and the IRCF bits are configured for an INTOSC frequency.
2. POR is executed, internal RC oscillator is selected via the SCS bits or Configuration Word 1 and the IRCF bits are configured for an INTOSC frequency.

3. The INTRC (31.25 kHz) is clocking the device and a switch to an INTOSC frequency is executed via modification of the IRCF bits.
4. An alternative oscillator selection is clocking the device (i.e., HS mode) and a clock switch to the internal RC oscillator is executed via the SCS bits with the IRCF bits configured for an INTOSC frequency.

Work around

Implement the following software delay shown in Example 1 after an INTOSC frequency has been enabled and before any frequency dependent application code is executed. This routine will delay application execution approximately 2K-150K Tcy (instruction cycles are dependent upon the INTOSC frequency) to ensure a stable INTOSC frequency.

Date Codes that pertain to this issue:

All date codes.

EXAMPLE 1: DELAY ROUTINE

```
DlyVarH    equ    <define address based on application requirements>
DlyVarL    equ    <define address based on application requirements>

;Load the delay variable DlyVarH with the following value for the selected frequency:
;125kHz 0x0300
;250kHz 0x0600
;500kHz 0x0C00
;1MHz 0x1900
;2MHz 0x3100
;4MHz 0x6200
;8MHz 0xC300

delay                                ;insure the correct data memory bank is selected
                                      ; for access of data variables
CLRF     DlyVarL                      ;initialize low delay variable
MOVLW   0x62                          ;initialize high delay variable
MOVWF   DlyVarH

dly_loop
DECFSZ  DlyVarL,f                      ;decrement low variable
GOTO    dly_loop
DECFSZ  DlyVarH,f                      ;decrement high variable
GOTO    dly_loop
RETURN                                     ;delay done
```

3. Module: PORTB Pull-ups

When $RBP\text{U} = 0$ (OPTION register), the PORTB weak pull-ups will not be disabled by the input functions of the SSP and/or CCP (Capture mode) module as indicated by the RB1:RB5 I/O block diagrams in **Section 5.0 "I/O Ports"**.

Work around

1. If the SSP and/or CCP (Capture mode) module is enabled, do not enable the PORTB weak pull-ups and use external pull-up resistors.

OR

2. If the SSP and/or CCP (capture mode) module and PORTB pull-ups are enabled, then evaluate the functionality of the SSP (I²C™/SPI™) or CCP (Capture mode) module to ensure proper operation within your application.

Date Codes that pertain to this issue:

All date codes.

PIC16F87/88

Clarifications/Corrections to the Data Sheet:

In the Device Data Sheet (DS30487B), the following clarifications and corrections should be noted.

1. Module: Voltage Reference Specifications

In Table 18-2 “Voltage Reference Specifications”, the Max value for specification #D311, Absolute Accuracy (VRAA Low Range) is incorrectly stated as 1/4 LSb. The correct value is 1/2 LSb.

The following table shows the change in **bold** text.

TABLE 18-2: VOLTAGE REFERENCE SPECIFICATIONS

Operating Conditions: 3.0V < VDD < 5.5V, -40°C < TA < +85°C, unless otherwise stated.							
Spec No.	Characteristics	Sym	Min	Typ	Max	Units	Comments
D310	Resolution	VRES	VDD/24	—	VDD/32	LSb	
D311	Absolute Accuracy	VRAA	—	—	1/2 1/2	LSb LSb	Low Range (VRR = 1) High Range (VRR = 0)
D312	Unit Resistor Value (R)*	VRUR	—	2k	—	Ω	
310	Settling Time ^{(1)*}	TSET	—	—	10	μs	

* These parameters are characterized but not tested.

Note 1: Settling time measured while VRR = 1 and VR<3:0> transitions from ‘0000’ to ‘1111’.

2. Module: Timer1 Oscillator and In-Circuit Serial Programming™

The following note has been added to clarify operation of the Timer1 oscillator when using In-Circuit Serial Programming or the In-Circuit Debugger.

This note was added to **Section 7.6 “Timer1 Oscillator”** and **Section 15.17 “In-Circuit Serial Programming”**.

Note: The Timer1 oscillator shares the T1OSI and T1OSO pins with the PGD and PGC pins used for programming and debugging.

When using the Timer1 oscillator, In-Circuit Serial Programming™ (ICSP™) may not function correctly (high voltage or low voltage), or the In-Circuit Debugger (ICD) may not communicate with the controller. As a result of using either ICSP or ICD operation, the Timer1 crystal may be damaged.

If ICSP or ICD operations are required, the crystal should be disconnected from the circuit (disconnect either lead), or installed after programming. The oscillator loading capacitors may remain in-circuit during ICSP or ICD operation.

3. Module: DC Characteristics

The maximum 2V, 4 MHz RC Oscillator specifications listed in **Section 18.2 “DC Characteristics”** of the device data sheet are incorrectly stated.

The following table shows the current test limits (modified values are shown in **bold**).

18.2 DC Characteristics: Power-down and Supply Current PIC16F87/88 (Industrial) PIC16LF87/88 (Industrial)

PIC16LF87/88 (Industrial)		Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for industrial						
PIC16F87/88 (Industrial)		Standard Operating Conditions (unless otherwise stated) Operating temperature $-40^{\circ}\text{C} \leq T_A \leq +85^{\circ}\text{C}$ for industrial						
Param No.	Device	Typ	Max	Units	Conditions			
	PIC16LF87/88	270	335	μA	-40°C	$V_{DD} = 2.0\text{V}$	Fosc = 4 MHz (RC Oscillator) ⁽³⁾	
			280	330	μA			$+25^{\circ}\text{C}$
			285	330	μA			$+85^{\circ}\text{C}$
	PIC16LF87/88	460	610	μA	-40°C	$V_{DD} = 3.0\text{V}$		
			450	600	μA			$+25^{\circ}\text{C}$
			450	600	μA			$+85^{\circ}\text{C}$
	All devices	900	1060	μA	-40°C	$V_{DD} = 5.0\text{V}$		
			890	1050	μA			$+25^{\circ}\text{C}$
			890	1050	μA			$+85^{\circ}\text{C}$

Legend: Shading of rows is to assist in readability of the table.

Note 1: The power-down current in Sleep mode does not depend on the oscillator type. Power-down current is measured with the part in Sleep mode, with all I/O pins in high-impedance state and tied to V_{DD} or V_{SS} and all features that add delta current disabled (such as WDT, Timer1 Oscillator, BOR, etc.).

2: The supply current is mainly a function of operating voltage, frequency and mode. Other factors, such as I/O pin loading and switching rate, oscillator type and circuit, internal code execution pattern and temperature, also have an impact on the current consumption.

The test conditions for all I_{DD} measurements in active operation mode are:

OSC1 = external square wave, from rail-to-rail; all I/O pins tri-stated, pulled to V_{DD} ;

MCLR = V_{DD} ; WDT enabled/disabled as specified.

3: For RC oscillator configurations, current through REXT is not included. The current through the resistor can be estimated by the formula: $I_r = V_{DD}/2\text{REXT}$ (mA) with REXT in $\text{k}\Omega$.

PIC16F87/88

REVISION HISTORY

Rev A Document (9/2003)

First revision of this document. Data Sheet Clarification issue 1 (Voltage Reference Specifications).

Rev B Document (2/2004)

Added Data Sheet Clarification issue 2 (Timer1 Oscillator and In-Circuit Serial Programming).

Rev C Document (4/2004)

Added silicon issue 1 (Internal RC Oscillator).

Rev D Document (6/2004)

Updated silicon issue 1 (Internal RC Oscillator) and added Data Sheet Clarification issue 3 (DC Characteristics).

Rev E Document (9/2004)

Added silicon issue 2 (Internal RC Oscillator IOFS bit) and 3 (PORTB Pull-ups).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip's products as critical components in life support systems is not authorized except with express written approval by Microchip. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, microID, MPLAB, PIC, PICmicro, PICSTART, PRO MATE, PowerSmart, rfPIC, and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.


AmpLab, FilterLab, MXDEV, MXLAB, PICMASTER, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, dsPICDEM, dsPICDEM.net, dsPICworks, ECAN, ECONOMONITOR, FanSense, FlexROM, fuzzyLAB, In-Circuit Serial Programming, ICSP, ICEPIC, Migratable Memory, MPASM, MPLIB, MPLINK, MPSIM, PICkit, PICDEM, PICDEM.net, PICLAB, PICtail, PowerCal, PowerInfo, PowerMate, PowerTool, rLAB, rfPICDEM, Select Mode, Smart Serial, SmartTel and Total Endurance are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2004, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

**QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==**

Microchip received ISO/TS-16949:2002 quality system certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona and Mountain View, California in October 2003. The Company's quality system processes and procedures are for its PICmicro® 8-bit MCUs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
480-792-7627
Web Address:
www.microchip.com

Atlanta
Alpharetta, GA
Tel: 770-640-0034
Fax: 770-640-0307

Boston
Westford, MA
Tel: 978-692-3848
Fax: 978-692-3821

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo
Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

San Jose
Mountain View, CA
Tel: 650-215-1444
Fax: 650-961-0286

Toronto
Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing
Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu
Tel: 86-28-8676-6200
Fax: 86-28-8676-6599

China - Fuzhou
Tel: 86-591-750-3506
Fax: 86-591-750-3521

China - Hong Kong SAR
Tel: 852-2401-1200
Fax: 852-2401-3431

China - Shanghai
Tel: 86-21-6275-5700
Fax: 86-21-6275-5060

China - Shenzhen
Tel: 86-755-8290-1380
Fax: 86-755-8295-1393

China - Shunde
Tel: 86-757-2839-5507
Fax: 86-757-2839-5571

China - Qingdao
Tel: 86-532-502-7355
Fax: 86-532-502-7205

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-2229-0061
Fax: 91-80-2229-0062

India - New Delhi
Tel: 91-11-5160-8632
Fax: 91-11-5160-8632

Japan - Kanagawa
Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Seoul
Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Singapore
Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Kaohsiung
Tel: 886-7-536-4816
Fax: 886-7-536-4817

Taiwan - Taipei
Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Taiwan - Hsinchu
Tel: 886-3-572-9526
Fax: 886-3-572-6459

EUROPE

Austria - Weis
Tel: 43-7242-2244-399
Fax: 43-7242-2244-393

Denmark - Ballerup
Tel: 45-4420-9895
Fax: 45-4420-9910

France - Massy
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Ismaning
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

England - Berkshire
Tel: 44-118-921-5869
Fax: 44-118-921-5820

08/24/04