

## ERRATA

For PCBs marked with JE2206C REV F, the bottom-most pad of R7 (circled below) did not get connected to the trace during PCB manufacturing. It can be fixed by installing a jumper from the unconnected pad of R7 to the pad of R1 nearest the edge of the board (boxed area below).

