



**UL International, L.L.C.,
Taiwan Branch**

美商優力安全認證有限公司台灣分公司
UL International, L.L.C., Taiwan Branch
台北市112北投區大業路260號1樓
1st Fl 260 Da-Yeh Road Peltou Taipei City Taiwan 112
tel: 886-2-2890-7790 fax: 886-2-2891-7644
http://www.ul.com.tw

NOTICE OF AUTHORIZATION TO APPLY THE UL MARK

June 15, 2005

Sparkle Power International Ltd.
22 Jianguo E Rd
Taoyuan Taiwan

Fax number: (03)357-9724

Reference: File E161885 Project 05CA15448 P.O. Number 94-0287
Product: For UL & C-UL Investigation, Switching Power Supply, Models AAT-2015, SPI-150G, SPI-200G, SPI-230G, SPI-250G, SPI-300G, TK-200GPS2, TK-200GPS3, FSP200-40GW and FSP145-40GW, Employing the Evaluation to UL60950-1.

Dear Mr. Allen Cheng

Any information and documentation provided to you involving UL Mark services are provided on behalf of Underwriters Laboratories Inc.

UL's Investigation of your products has been completed under the above project number and the subject products were determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Recognized Marking and/or Recognized Component Mark only at the factory under UL's Follow-Up Services Program to the subject products which are constructed as described below:

Similar to Switching Power Supply, Models AAT-2015, SPI-150G, SPI-200G, SPI-230G, SPI-250G, SPI-300G, TK-200GPS2, TK-200GPS3, FSP200-40GW and FSP145-40GW, covered in the UL Follow-Up Services Procedure, File E161885, Volume 1, Section 1, except for employing the evaluation to UL60950-1.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E161885, Volume 1.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Jason Ku
6.15.2005

Jason Ku
Engineer
UL International, L.L.C., Taiwan Branch
Tel: (02)2896-7790 Ext. 62045
Fax: (02)2890-7442
E-mail: Jason.Ku@tw.ul.com

Reviewed by:

Joe Lin
6.15.2005

Joe Lin
Project Engineer
Department: 3000A TPI
E-mail: Joe.Lin@tw.ul.com

CC: PSE Inc. Taiwan Fax: (02)2995-9169 Attn: Ms. Erica Chen

An independent organization working for a safer world with integrity, precision and knowledge





**UL International, L.L.C.,
Taiwan Branch**

美商優力安全認證有限公司台灣分公司
UL International, L.L.C., Taiwan Branch
台北市 112 北投區大業路 280 號 1 樓
1st Fl 280 Da-Yeh Road Beitou Taipei City Taiwan 112
tel: 886-2-2896-7790 fax: 886-2-2891-7644
http://www.ul.com.tw

Fax Cover

Date	June 15, 2005
Attention:	Mr. Allen Cheng
Company:	Sparkle Power International Ltd.
Fax Number:	(03)357-9724 空號
CC:	Ms. Erica Chen
Company:	PSE Inc. Taiwan
Fax Number:	(02)2995-9169
From:	Jason Ku
Fax Number:	886-2-2891-7644
Phone Number:	886-2-2896-7790

THIS MESSAGE AND ANY DOCUMENTS ACCOMPANYING IT IS INTENDED ONLY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHICH IT IS ADDRESSED AND MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, AND EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. If the reader of this message is not the intended recipient, or the employee or agent responsible for delivering the message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received the communication in error, please notify us immediately by return fax and advise whether you have destroyed the original message or are returning it to us through the mail.

IF YOU EXPERIENCE A PROBLEM RECEIVING THIS TRANSMISSION, PLEASE CALL.

TOTAL PAGES, INCLUDING COVER: 2

<input type="checkbox"/> Urgent	<input type="checkbox"/> Reply ASAP	<input type="checkbox"/> Please Comment	<input type="checkbox"/> Please Review	<input checked="" type="checkbox"/> For Your Information
---------------------------------	-------------------------------------	---	--	--

Our Reference: File E161885 Project 05CA15448

Your Reference:

Subject: For UL & C-UL Investigation, Switching Power Supply, Models AAT-2015, SPI-150G, SPI-200G, SPI-230G, SPI-250G, SPI-300G, TK-200GPS2, TK-200GPS3, FSP200-40GW and FSP145-40GW, Employing the Evaluation to UL60950-1.

An independent organization working for a safer world with integrity, precision and knowledge

